


**TOYOTA AVENSIS TOURING SPORTS: 1NJU813**

Vinnumber:	<b>SB1EG76L90E120804</b>	Versionname:	<b>1.8 VALVEMATIC DYNAMIC+ MD S AUTO</b>
First Registrationdate:	<b>7/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>81481</b>	Power Kw:	<b>108</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2323</b>
Maintenance:	<b>20-3-2018</b>		
Maintenance:	<b>77328 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage:	<b>HD</b>	Central consol F:	
GPS storage:		Luggage cover:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning:	<b>OK</b>	Battery functioning:	<b>Yes</b>
Tires wear profile:	<b>OK</b>	Power steering:	<b>Yes</b>
Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Wiper fluid level:	<b>OK</b>
Handbrake:	<b>OK</b>	Transmission:	<b>OK</b>
		Lighting:	<b>OK</b>
		Wiperblades:	<b>OK</b>

**Degree of wear**

	<b>225/45/18/95 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
-------------	------------	-------------	------------

Total cost ex VAT	95,00
-------------------	-------

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------





Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	