



RENAULT Megane: 1FVB456

Vinnnumber:	VF1BZ1A0749472685	Versionname:	MEGANE BER Authentique 90PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	106810	Power Kw:	66
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2893,11
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35



Seat cover F L, Damaged, E - Replace	360,00
--------------------------------------	--------



Wheel cover R L, Scratch(es), E - Replace	30,00
---	-------



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Bad repair, Paint 0,00



Wing R R, Bump(s), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18




Wheel cover R R, Missing, E - Replace 30,00



Wheel cover F L, Damaged, E - Replace 30,00



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Wheel cover F R, Missing, E - Replace 30,00



Wing R L, Bump(s), LI - Repair and paint (complete) 308,20

