



<b>RENAULT Trafic: 1GKS869</b>			
Vinnnumber:	<b>VF1FLB1B8EY547402</b>	Versionname:	<b>TRAFIC 29 B/F L2H1 Gr.Conf.FAP(EU5)115PK</b>
First Registrationdate:	<b>5/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>173838</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV06</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
Winter tyres:	<b>215/65/16/109 R LightMetal</b>			
	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>2268,69</b>
Bumper R, Scratch(es), Smart repair			<b>110,64</b>



Roof, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door F R, Accident, Le - Replace and paint	<b>847,88</b>



Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>158,85</b>
---	---------------



Sidewall FL (LCV), Bump(s), Acceptable 0,00

No pictures to display

Wing F R, Accident, Le - Replace and paint 427,51



Bumper F R, Scratch(es), Smart repair 110,64



Sliding door R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15

