


**RENAULT Megane: 1FWY763**

Vinnnumber:	<b>VF1KZ140649813032</b>	Versionname:	<b>MEGANE GT Energy Bose Ed.110PK</b>
First Registrationdate:	<b>22/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>115081</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>		
Maintenance:	<b>4400 KM OF 14 MND</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>SD</b> Luggage cover
GPS storage	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-leather</b>
Adaptive cruise control	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

205/50/17/89 V LightMetal				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1139,03
-------------------	---------

Bumper moulding F, Scratch(es), E - Replace	14,40
---	-------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper moulding F M, Scratch(es), E - Replace

14,40



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Bumper moulding F R, Broken, Le - Replace and paint

100,00



Seat cover F L, Worn, P - Check

0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

