


RENAULT CLIO IV BREAK: 1GQG381

Vinnumber:	VF17R040H50102992	Versionname:	Expression 75PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	61996	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK		
Maintenance:	OH UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	886,77
-------------------	---------------

Seat cover F L, Hole, E - Replace	312,00
-----------------------------------	---------------





Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
Maintenance, Maintenance, Execute	0,00
	
Wheel cover F R, Scratch(es), E - Replace	24,00
	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), LI - Repair and paint (complete)	385,20



Door F L, Scratch(es), 67 - Polish	55,19
------------------------------------	-------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Scratch(es), 67 - Polish	55,19
----------------------------------	-------



Wing R L, Scratch(es), 67 - Polish	55,19
------------------------------------	-------

