



VOLKSWAGEN GOLG GTI: ZW1337

Vinnumber:	WVWZZZAUZGW048954	Versionname:	
First Registrationdate:	28/07/2015	Fiscalpower:	
Expertise Mileage:	98790	Power Kw:	169
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	3426
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining Alcantara	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			298,20
Wing R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Tyre F L, Worn, Forfeit			0,00
<i>No pictures to display</i>			
Ignition key, Not functioning (well), Repair/replace (lump sum)			0,00
<i>No pictures to display</i>			
Alloy rim F R polished, Damaged, E - Replace			235,20



Tyre F R, Worn, Forfeit	0,00
-------------------------	------



Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display