



## VOLVO V60: 1GXQ773

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                        | <b>YV1FW8481F1217960</b> | Versionname: | <b>V60 BRE D2 Kinetic 115PK</b> |
| First Registrationdate:            | <b>28/05/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>117776</b>            | Power Kw:    | <b>84</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2322</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

## Options

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| GPS storage                    |                              | Luggage cover        |                          |
| GPS storage                    | <b>HD</b>                    | Rear parking sensors |                          |
| Windows electric F             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |                              |                      |                          |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Seats F heated                 |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                      |       |                      |
|---------------|----------------------------------|----------------------|-------|----------------------|
|               | <b>215/50/17/95 W LightMetal</b> |                      |       |                      |
| Summer tyres: | Fr.L.                            | <b>Pirelli: 6 mm</b> | Fr.R. | <b>Pirelli: 6 mm</b> |
|               | Re.L.                            | <b>Pirelli: 5 mm</b> | Re.R. | <b>Pirelli: 5 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |        |
|--|--------|
| Total cost ex VAT                      | 140,00 |
| Alloy rim R R, Scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>          |        |
| Bonnet, Scratch(es), Acceptable        | 0,00   |
| <i>No pictures to display</i>          |        |
| Seat cover R R, Stain, Acceptable      | 0,00   |
| <i>No pictures to display</i>          |        |
| Wing R L, Scratch(es), Acceptable      | 0,00   |
| <i>No pictures to display</i>          |        |
| Wing F L, Scratch(es), Acceptable      | 0,00   |
| <i>No pictures to display</i>          |        |
| Seat cover F R, Stain, Cleaning        | 25,00  |



|   |        |
|---|--------|
| Wing R R, Bump(s), Acceptable                         | 0,00   |
| <i>No pictures to display</i>                         |        |
| Door R L, Scratch(es), Acceptable                     | 0,00   |
| <i>No pictures to display</i>                         |        |
| Alloy rim F R, Scratch(es), Acceptable                | 0,00   |
| <i>No pictures to display</i>                         |        |
| Bumper R, Scratch(es), Acceptable                     | 0,00   |
| <i>No pictures to display</i>                         |        |
| Glove compartment lid, Scratch(es), Acceptable        | 0,00   |
| <i>No pictures to display</i>                         |        |
| Rocker panel inner F L, Scratch(es), It - Spot repair | 115,00 |



|                                   |      |
|-----------------------------------|------|
| Seat cover F L, Stain, Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |