



TOYOTA YARIS: YX7373

Vinnumber:	VNKKD3D360A291978	Versionname:	1.5 VVT-I HYBRID DYNAMIC AUTO
First Registrationdate:	12/01/2017	Fiscalpower:	
Expertise Mileage:	36065	Power Kw:	74
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3313
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/65/15/84 H Steel				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
175/65/15/88 T None				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2578,18
Bumper R, Scratch(es), LI - Repair and paint (complete)			169,44



Door R L, Accident, Le - Replace and paint

786,33



Rearlight L, Damaged, E - Replace 96,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R L, Damaged, E - Replace 84,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Roof, Scratch(es), LI - Repair and paint (complete) 385,20



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Accident, Le - Replace and paint 1033,21

