



## VOLKSWAGEN TIGUAN: 1GUK461

Vinnnumber:	<b>WVGZZZ5NZEW615647</b>	Versionname:	<b>TIGUAN Sport&amp;Style BM Tech.140PK</b>
First Registrationdate:	<b>5/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>70858</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
GPS storage		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunction		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/17/96 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	259,80
-------------------	--------

Door F R, Bad repair, Acceptable	0,00
----------------------------------	------





Wing trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Shutter / cover, Unclamped, N - Mount/Dismount 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Not original part, Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Repaired, Acceptable 0,00



Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Acceptable 0,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Shutter / cover, Unclamped, N - Mount/Dismount 0,00



Bodywork, Dirty, Acceptable 0,00





Door R L, Repaired, Acceptable 0,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 259,80



Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Tires, Out of tolerance, Acceptable 0,00



Seat F L compl, Worn, Acceptable 0,00



Wing F R, Repaired, Acceptable 0,00



Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door frame F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Repaired, Acceptable 0,00



Glove compartment lid, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	