



| VOLVO XC60: 1PDP196 | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | YV1DZARC1H2012360 | Versionname: | 2.0 D3 2WD MOMENTUM |
| First Registrationdate: | 10/06/2016 | Fiscalpower: | |
| Expertise Mileage: | 50917 | Power Kw: | 110 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1532 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining semi-leather |
| Type of climate control: | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 235/65/17/108 V LightMetal | | | |
| Winter tyres: | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm |
| | Re.L. | Uniroyal: 4 mm | Re.R. | Uniroyal: 4 mm |

| Assistance equipment | | | |
|---|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | 264,21 | |
| Bumper R, Scratch(es), Acceptable | | 0,00 | |
| <i>No pictures to display</i> | | | |
| Wing R L, Scratch(es), Acceptable | | 0,00 | |
| <i>No pictures to display</i> | | | |
| Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) | | 264,21 | |

