



VOLVO V40: 1EZB408

| | | | |
|-------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber: | YV1MV8481D2056960 | Versionname: | V40 D2 Base 115PK |
| First Registrationdate: | 25/04/2013 | Fiscalpower: | |
| Expertise Mileage: | 92402 | Power Kw: | 84 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 2614 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

Options

| | | | |
|--------------------------------|------------------------------|------------------|--|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS portable | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|---------------------------------|-----------------------|-------|-----------------------|
| | 205/5/15/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1753,08 |
|-------------------|----------------|

| | |
|---|---------------|
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|---------------|



| | |
|-------------------------------|-------------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|--|---------------|
| Bonnet, Chemical pollution, LI - Repair and paint (complete) | 290,08 |
|--|---------------|



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Gear shift lever knob, Damaged, E - Replace 114,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

