



VOLKSWAGEN Touran: 1GG5843

Vinnnumber:	WVGZZZ1TZEW046893	Versionname:	TOURAN Highline BMT Start/Stop 105PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	7535	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE -70D		
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1287,56
-------------------	----------------

Sill outer R, Bump(s) and scratch(es), It - Spot repair	115,56
---	---------------



Interior, Worn, Acceptable	0,00
----------------------------	-------------



Maintenance, Maintenance, Execute 0,00



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Wing R L, Bump(s), PDR - Knock out without painting 63,00




Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper Trim F, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Engine protective plate, Hole, E - Replace 96,20



Backrest cover R L, Broken, Acceptable 0,00

No pictures to display