



VOLVO V40: 1GRY597			
Vinnnumber:	YV1MV8481E2149737	Versionname:	V40 D2 Base 115PK
First Registrationdate:	11/04/2014	Fiscalpower:	
Expertise Mileage:	103629	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1625
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			923,35
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80



Door F L, Bump(s), LI - Repair and paint (complete)			318,35
---	--	--	---------------



Alloy rim F L, Damaged, E - Replace

235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Bump(s), Acceptable

0,00

No pictures to display

Sill outer L, Bump(s), PDR - Knock out without painting

63,00



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display