



|                           |                          |              |                                       |
|---------------------------|--------------------------|--------------|---------------------------------------|
| <b>VOLVO S60: 1FEY435</b> |                          |              |                                       |
| Vinnumber:                | <b>YV1FS84A1D2224222</b> | Versionname: | <b>S60 BER D2 Kinetic St/St 115PK</b> |
| First Registrationdate:   | <b>11/06/2013</b>        | Fiscalpower: |                                       |
| Expertise Mileage:        | <b>141745</b>            | Power Kw:    | <b>84</b>                             |
| Bodytype:                 |                          | Body color   | <b>Dark Grey</b>                      |
| Gearbox:                  | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                        |
| Transmission:             |                          | Rims summer  | <b>Aluminium</b>                      |
| Fueltype:                 | <b>Diesel</b>            | Oil level    | <b>OK</b>                             |
| Battery functioning       | <b>Yes</b>               | Parking lot  | <b>2115</b>                           |
| Number of doors           | <b>4</b>                 |              |                                       |
| Number of seats           | <b>5</b>                 |              |                                       |
| Number head rests         | <b>5</b>                 |              |                                       |
| Rims summer               | <b>Aluminium</b>         |              |                                       |
| Category                  | <b>Passenger Car</b>     |              |                                       |
| Oil level                 | <b>OK</b>                |              |                                       |

|                                |                              |
|--------------------------------|------------------------------|
| <b>Options</b>                 |                              |
| Radio CD                       | Central consol F             |
| Windows electric F             | Rear parking sensors         |
| Windows electric R             |                              |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>235/45/17/97 H LightMetal</b> |                       |       |                       |
| Winter tyres:         | Fr.L.                            | <b>Goodyear: 7 mm</b> | Fr.R. | <b>Goodyear: 7 mm</b> |
|                       | Re.L.                            | <b>Goodyear: 6 mm</b> | Re.R. | <b>Goodyear: 6 mm</b> |

|   |            |            |                |
|---|------------|------------|----------------|
| <b>Assistance equipment</b>   |            |            |                |
| Repair kit  | <b>Yes</b> | Compressor | <b>Yes</b>     |
| <b>Total cost ex VAT</b>  |            |            | <b>1340,08</b> |
| <b>Alloy rim R R, Scratch(es), LI - Repair and paint (complete)</b> |            |            | <b>95,00</b>   |



|   |  |  |              |
|---|--|--|--------------|
| <b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b> |  |  | <b>95,00</b> |
|---|--|--|--------------|



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Roof, Hail damage, PDR - Hail 150,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



