



AUDI A6: 1GTQ171			
Vinnnumber:	WAUZZZ4G0EN122504	Versionname:	A6 BER Multitr.136PK Aut.
First Registrationdate:	25/04/2014	Fiscalpower:	
Expertise Mileage:	167146	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3603
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			150,00
Wing F L, Scratch(es), LI - Repair and paint (complete)			0,00



Door F R, Scratch(es), LI - Repair and paint (complete)			0,00
--	--	--	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display