



BMW 3: 1GTU761			
Vinnnumber:	WBA3Y11080D449636	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	28/04/2014	Fiscalpower:	143PK
Expertise Mileage:	102659	Power Kw:	105
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2119
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		


Options	
Radio CD	Sun Roof electric
TV/DVD screen R	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/18/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	95,00
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	