



BMW 3: 1BCH049

Vinnumber:	WBAUT31000F019117	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	2/05/2011	Fiscalpower:	
Expertise Mileage:	134166	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2214
Maintenance:	IN 19000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	793,60
-------------------	---------------

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------------------	---------------





Alloy rim R L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Worn, Acceptable	0,00
--------------------------------------	------

No pictures to display

Door panel F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Front bumper, Damaged, LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Outer door handle F L, Scratch(es), Acceptable	0,00
------------------------------------------------	------

No pictures to display