



## CITROEN C4 Picasso: 1GMB831

Vinnumber:	<b>VF73A9HC8DJ843127</b>	Versionname:	<b>GR.C4 PICASSO Business GPS 115PK</b>
First Registrationdate:	<b>7/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>143029</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2604</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 1481,51

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Air vent mid-dashboard, Damaged, E - Replace 156,00




Door panel R R, Dirty, Cleaning

25,00



Ceiling, Stain, Cleaning

25,00



Rear window, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Bump(s) and scratch(es), Acceptable

0,00



Door frame R L, Bump(s) and scratch(es), It - Spot repair

115,56



Interior, Stain, Cleaning 50,00



Door panel R L, Dirty, Cleaning 25,00



Outer backrest protection L, Damaged, E - Replace 35,00



Outer backrest protection R, Damaged, E - Replace 35,00



Sill trim F L, Tear, E - Replace 20,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s), PDR - Knock out without painting 63,00



Door F R, Scratch(es), Acceptable 0,00

