



**BMW 3: 1GUH302**

Vinnnumber:	<b>WBA3E11040F946910</b>	Versionname:	<b>3 BER 320dA Eff.Dynamics</b>
First Registrationdate:	<b>2/05/2014</b>	Fiscalpower:	<b>Ed.163PK Aut.</b>
Expertise Mileage:	<b>49801</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Light Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1413</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	2508,09
Roof, Chemical polution, LI - Repair and paint (complete)	220,18



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Bumper R, Damaged, Le - Replace and paint 651,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 307,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

