


FORD FOCUS CLIPPER: 1PZT301

| | | | |
|-----------------------------------|--------------------------|--------------|---|
| Vinnnumber: | WF06XXGCC6FP02151 | Versionname: | 1.0I ECOBOOST 92KW S/S BUSINESS CLASS+ |
| First Registrationdate: | 20/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 41503 | Power Kw: | 92 |
| Bodytype: | | Body color | Brown |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Petrol | Oil level | OK |
| Maintenance | OK | Parking lot | 2226 |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------|-------|--------------------|
| | 205/55/16/94 V LightMetal | | | |
| Winter tyres: | Fr.L. | Fulda: 4 mm | Fr.R. | Fulda: 4 mm |
| | Re.L. | Fulda: 7 mm | Re.R. | Fulda: 7 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 413,35 |
|-------------------|--------|

| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



| | |
|-----------------------------------|------|
| Wing F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|------|
| Front bumper, Stone chip(s), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|----------------------------|------|
| Ceiling, Dirty, Acceptable | 0,00 |
|----------------------------|------|



| | |
|--|------|
| Bumper corner R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display