


BMW 3: 1HHT428

Vinnumber:	WBA3J31070F813646	Versionname:	3 BER 318dX 143PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	158079	Power Kw:	105
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4331
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1022,06
Door R R, Scratch(es), Acceptable		0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	---------------






Registration Document, Missing, E - Replace 150,00

No pictures to display

Front bumper, Bad repair, Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Chemical polution, LI - Repair and paint (complete) 220,18



Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display