


FORD Focus: 1EQD381

Vinnumber:	WF0LXXGCBCT36024	Versionname:	FOCUS CLIP. EConetic T.Titanium 115PK
First Registrationdate:	20/02/2013	Fiscalpower:	
Expertise Mileage:	183027	Power Kw:	85
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2733
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment























Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	900,10
-------------------	--------

Ceiling, Stain, Acceptable	0,00
----------------------------	------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

  	Wing R L, Bump(s), PDR - Knock out without painting	150,60
  	Gear shift lever cover, Worn, Acceptable	0,00
 	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
 	Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
 	Fuel cap cover, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
  	Alloy rim F R, Damaged, E - Replace	235,20
  	Bumper corner R L, Scratch(es), It - Spot repair	115,56
 	Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
 	Wing F R, Damaged, LI - Repair and paint (complete)	220,18
	Door R R, Bump(s), PDR - Knock out without painting	63,00