


FORD C-MAX: 1DOK743

Vinnnumber:	WFOJXXWPBJCK09528	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	6/07/2012	Fiscalpower:	
Expertise Mileage:	159923	Power Kw:	70
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2510
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 H LightMetal				
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2257,88
-------------------	---------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Damaged, Le - Replace and paint	651,00
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Rearlight R tailgate, Damaged, E - Replace	114,00
--	--------



Tailgate, Damaged, Le - Replace and paint	1034,68
---	---------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

