


**RENAULT Grand Scenic: 1DKE035**

Vinnumber:	<b>VF1JZ00AD47372322</b>	Versionname:	<b>GR.SCENIC Energ.Privilège</b>
First Registrationdate:	<b>7/06/2012</b>	Fiscalpower:	<b>5pl.FAP 130PK</b>
Expertise Mileage:	<b>110211</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3815</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather and alcantara</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 1171,66

**Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)** 0,00

**Alloy rim F R, Scratch(es), LI - Repair and paint (complete)**
**95,00**



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bonnet, Chemical pollution, LI - Repair and paint (complete) 0,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Ceiling, Hole, Smart repair 64,32



Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

