



PEUGEOT 508: QW4920			
Vinnnumber:	VF38ERHR8DL022205	Versionname:	508 SW Allure 136PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	154333	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/55/17/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			811,98
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
---	--	--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

