



## MINI Countryman: 1HDP321

Vinnumber:	<b>WMWZD31020WS18592</b>	Versionname:	<b>MINI COUNTRYMAN Cooper D DPF 112PK</b>
First Registrationdate:	<b>25/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>164882</b>	Power Kw:	<b>82</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2106</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

## Assistance equipment

Total cost ex VAT	1451,54
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Alloy rim F L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
-------------------------------------------------------------------	--------



Windscreen, Scratch(es), E - Replace 20,40



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display


Number plate light L, Damaged, I - Repair 24,00



Rear window, Scratch(es), E - Replace 370,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Ignition key, Missing, E - Replace 150,00

No pictures to display