




MERCEDES CLA SHOOTING BRAKE: 1NUB095				
Vinnumber:	WDD1179081N314775	Versionname:	CLA 200 d	
First Registrationdate:	27/04/2016	Fiscalpower:		
Expertise Mileage:	55813	Power Kw:	100	
Bodytype:		Body color	Black	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	OK	Parking lot	2826	
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Sun Roof electric		
GPS storage		Panoramic roof		
GPS storage	HD	Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Seats F heated				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather and alcantara			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/40/18/92 Y LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			845,15	
Mirror side blinker R, Broken, E - Replace			30,00	
				
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35	



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

