



RENAULT Megane: 1FVB354

Vinnnumber:	VF1BZ1A0749472666	Versionname:	MEGANE BER Authentique 90PK
First Registrationdate:	4/11/2013	Fiscalpower:	90PK
Expertise Mileage:	114757	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2823
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 9 mm	Fr.R.	Uniroyal: 9 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2475,39
-------------------	---------

Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Interior, Dirty, Cleaning	125,00
---------------------------	--------





Wheel cover F R, Damaged, E - Replace 30,00



Bodywork, Not original part, Acceptable 0,00



Wheel cover F L, Damaged, E - Replace 30,00



Backrest cover F L, Hole, E - Replace 360,00



Dashboard, Hole, Smart repair 110,64



Door frame F R, Bump(s) and scratch(es), It - Spot repair 115,56



Wheel cover R L, Damaged, E - Replace 30,00





Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Interior, Smell, Ozone treatment	152,58
----------------------------------	--------



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Roof, Damaged, LI - Repair and paint (complete)	481,50
---	--------



Luggage space cover, Damaged, E - Replace	10,00
---	-------



Ceiling, Hole, Smart repair	64,32
-----------------------------	-------




Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wheel cover R R, Damaged, E - Replace 30,00

