



<b>OPEL Astra: 1EDM412</b>			
Vinnnumber:	<b>W0LPD6EW5DG025376</b>	Versionname:	<b>ASTRA BER ecoFLEX Enjoy St/St 110PK</b>
First Registrationdate:	<b>29/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>62233</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1322</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


<b>Degree of wear</b>				
	<b>215/60/16/99 H Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 8 mm</b>	Fr.R.	<b>Fulda: 8 mm</b>
	Re.L.	<b>Fulda: 8 mm</b>	Re.R.	<b>Fulda: 8 mm</b>


<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	486,60
Wing R L; Bump(s); PDR - Knock out without painting	63,00



Bonnet, Chemical polution, LI - Repair and paint (complete)	0,00
---	------





Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00

