



**PEUGEOT PARTNER TEPEE: 1LGC001**

Vinnnumber:	<b>VF37JBHMFJ793666</b>	Versionname:	<b>1.6 BLUEHDI 88KW S/S TEPEE ACTIVE</b>
First Registrationdate:	<b>18/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>200559</b>	Power Kw:	<b>88</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2116</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

GPS storage		Rear parking sensors	
GPS storage	<b>HD</b>		
Cruise Control			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/15/92 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>No</b>	Jack	<b>No</b>
-----------------------	-----------	------	-----------










Total cost ex VAT 2729,20

Sill outer L, Scratch(es), LI - Repair and paint (complete) 232,88



Interior, Dirty, Cleaning 50,00



	Rearlight R , Scratch(es), Acceptable	0,00
	Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	206,85
	Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
	Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>		
	Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
	Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
	Door F L, Scratch(es), LI - Repair and paint (complete)	238,76
	Luggage space cover, Missing, E - Replace	50,00
	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	255,15
	Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15



Spare wheel, Missing, E - Replace

153,60



Door R L, Scratch(es), LI - Repair and paint (complete)

238,76



Jack, Missing, E - Replace

42,00

No pictures to display

Internal Boot Lining L, Hole, E - Replace

62,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)

304,88

