


PEUGEOT 5008: 1GTU777

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnnumber: | VF30A9HD8E5094226 | Versionname: | 5008 e-HDi Allure STT BMP 115PK Aut. |
| First Registrationdate: | 28/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 150033 | Power Kw: | 84 |
| Bodytype: | MPV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3706 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------|------------------------------|
| Radio CD | Panoramic roof |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Autom climate control |
| Head-up Display | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | 215/55/16/93 V LightMetal | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|--------|
| Total cost ex VAT | 729,43 |
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |



| | |
|---|--------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Bump(s), LI - Repair and paint (complete) | 390,35 |



| | |
|--|-------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper grille, Damaged, E - Replace | 49,00 |

