



**PEUGEOT 308: 1EXC180**

Vinnumber:	<b>VF34C9HP0DS051860</b>	Versionname:	<b>1.6 HDI</b>
First Registrationdate:	<b>11/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>64163</b>	Power Kw:	<b>68</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>- 4400 KM</b>	Parking lot:	<b>2303</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>N.D.</b>
	Re.L.	<b>N.D.</b>	Re.R.	<b>N.D.</b>
	<b>205/55/16/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>N.D.</b>	Fr.R.	<b>Pirelli: 3 mm</b>
	Re.L.	<b>N.D.</b>	Re.R.	<b>N.D.</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1157,48</b>
--------------------------	----------------

<b>Wheel cover F L, Scratch(es), E - Replace</b>	<b>30,00</b>
--	--------------





Bumper trim R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R L, Scratch(es), E - Replace 30,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door trim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Seat cover F L, Stain, Cleaning 25,00



Door trim F R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Door trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F M, Scratch(es), E - Replace 14,40



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Scratch(es), E - Replace 32,40



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Tyre F L, Damaged, E - Replace 132,00

