



VOLVO V40: 1HGB574

Vinnumber:	YV1MV8461F2184315	Versionname:	V40 D2 Base 115PK
First Registrationdate:	11/07/2014	Fiscalpower:	
Expertise Mileage:	177336	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3701
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather and alcantara
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/93 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1134,12
-------------------	---------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F R, Bump(s), Acceptable 0,00

No pictures to display


Seat cover F L, Hole, Smart repair 64,32



Alloy rim F L, Damaged, E - Replace 235,20



First-aid kit, Empty, E - Replace 25,00



Bumper grille, Broken, E - Replace 32,40



Alloy rim R L, Damaged, E - Replace 235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Damaged, E - Replace 235,20

