



VOLKSWAGEN PASSAT: 1GUG592

Vinnumber:	WVWZZZAUZEP590560	Versionname:	
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	202218	Power Kw:	
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1586,63
-------------------	---------


Trunk lid covering R, Damaged, Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display











Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

<i> bumper (r), scratch(es), LI - Repair and paint (complete)</i>		
		
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Wing R R, Hole, LI - Repair and paint (complete)		308,20
		
Sill outer R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Bump(s), LI - Repair and paint (complete)		318,35
		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		