



VOLVO V60: 1EUS811

Vinnnumber:	YV1FW84A1D1134005	Versionname:	V60 D2 Kinetic St/St
First Registrationdate:	26/03/2013	Fiscalpower:	115PK
Expertise Mileage:	160239	Power Kw:	84
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2708
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/45/17/97 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	190,00
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	