



VOLKSWAGEN Caddy: 1DJT238

Vinnumber:	WV1ZZZ2KZCX158553	Versionname:	CADDY VAN B/F 75PK
First Registrationdate:	5/06/2012	Fiscalpower:	
Expertise Mileage:	129189	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	33,00
-------------------	--------------

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Supplementary brake lights, Damaged, E - Replace	33,00
--	--------------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Roof, Stone chip(s), Acceptable	0,00
---------------------------------	-------------

No pictures to display