



VOLKSWAGEN Touran: 1FVE412			
Vinnnumber:	<b>WVGZZZ1TZEW036690</b>	Versionname:	<b>TOURAN Highline BMT St/St DSG 140PK Aut.</b>
First Registrationdate:	<b>5/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>123871</b>	Power Kw:	<b>103</b>
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metallic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1505</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining Alcantara</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

Assistance equipment	
Spare wheel	<b>Yes</b>

Total cost ex VAT	<b>581,60</b>
Door F R, Bump(s) and scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bonnet, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>





Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Front bumper, Bump(s), LI - Repair and paint (complete) 211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*