



<b>VOLKSWAGEN Up: 1EDM399</b>			
Vinnumber:	<b>WVWZZAAZDD053186</b>	Versionname:	<b>UP BER Move up BMT 75PK</b>
First Registrationdate:	<b>29/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>69188</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1611</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS portable</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>175/65/14/82 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1300,70</b>
<b>Ignition key, Missing, E - Replace</b>	<b>150,00</b>

<i>No pictures to display</i>	
<b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b>	<b>169,44</b>



<b>Interior, Dirty, Cleaning</b>	<b>0,00</b>
----------------------------------	-------------



<b>Seat cover F L, Hole, E - Replace</b>	<b>312,00</b>
--	---------------



Roof pillar L, Bump(s), LI - Repair and paint (complete) 176,14



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56

