



VOLKSWAGEN Passat: 1ERW864

Vinnnumber:	WVWZZZ3CZDE096434	Versionname:	PASSAT VAR Comfortline
First Registrationdate:	5/03/2013	Fiscalpower:	136PK
Expertise Mileage:	137171	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1523
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3060,53
-------------------	---------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R L, Damaged, Le - Replace and paint	946,92
---	--------



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00




Ignition key, Missing, E - Replace 150,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

