


RENAULT Megane: 1GKX440

Vinnumber:	VF1KZ0R0250455530	Versionname:	MEGANE GT TomTom Edition 95PK
First Registrationdate:	6/03/2014	Fiscalpower:	
Expertise Mileage:	89093	Power Kw:	70
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	4703
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1675,03
-------------------	----------------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	---------------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	---------------




Window F L door, Scratch(es), E - Replace 120,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Chemical polution, LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper corner R R, Scratch(es), It - Spot repair 115,56

