



AUDI A5: SQ5429			
Vinnnumber:	<b>WAUZZZ8T6DA072074</b>	Versionname:	<b>A5 COU DPF 177PK</b>
First Registrationdate:	<b>17/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>132602</b>	Power Kw:	<b>130</b>
Bodytype:	<b>Coupé</b>	Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2108</b>
Number of doors	<b>4</b>		
Number of seats	<b>4</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Cruise Control	Central consol F
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>255/35/19/96 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

Assistance equipment	
Emergency spare wheel	<b>Yes</b>

Total cost ex VAT	2326,87
Door F L, Scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Bonnet, Stone chip(s), Acceptable 0,00  
No pictures to display

Bumper R, Scratch(es), Acceptable 0,00  
No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearlight L, Damaged, I - Repair 24,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Front bumper, Damaged, Le - Replace and paint 862,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Seat cover F L, Damaged, E - Replace

44,00

