



**AUDI Q7: 1EPB867**

Vinnnumber:	<b>WAUZZZ4L1DD021845</b>	Versionname:	<b>Q7 Start/Stop Tiptr.204PK Aut.</b>
First Registrationdate:	<b>12/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>69804</b>	Power Kw:	<b>150</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Light Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1515</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>275/45/20/110 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 7 mm</b>	Fr.R.	<b>Goodyear: 7 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>

**Assistance equipment**

Emergency spare wheel **Yes**

Total cost ex VAT	1593,68
Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------





Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

