

AUDI A3: 1FCY407

Vinnumber:	WAUZZZ8VXDA085461	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	28/05/2013	Fiscalpower:	
Expertise Mileage:	182733	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	2620
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1515,01
-------------------	----------------

Alloy rim F R, Bad repair, Repair/replace (lump sum)	0,00
--	-------------




Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Damaged, E - Replace

235,20



Rearview mirror L complete, Scratch(es), Smart repair

110,64



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18




Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Maintenance, Maintenance, Execute

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display

Boot carpet, Damaged, Repair/replace (lump sum)

0,00

