



FORD FIESTA: 1TDV243

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnnumber: | WF0JXXGAHJHC25502 | Versionname: | VIGNALE |
| First Registrationdate: | | Fiscalpower: | |
| Expertise Mileage: | 7666 | Power Kw: | 88 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2125 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|------------------------------|------------------------------|
| Windows electric F | Sun Roof electric |
| Windows electric R | Panoramic roof |
| Cruise Control | Central consol F |
| Steering wheel multifunction | Luggage cover |
| Seats F heated | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/40/18/86 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |


Assistance equipment

| | | |
|---|------------|------------|
| | Compressor | Yes |
| Total cost ex VAT | | 1266,68 |
| Rear spoiler, Scratch(es), LI - Repair and paint (complete) | | 115,56 |



Roof, Damaged, Le - Replace and paint

592,00



Spoiler roof, Scratch(es), It - Spot repair 115,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Luggage space cover, Damaged, E - Replace 20,00



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68

