



BMW 3: 1HXE375

Vinnumber:	WBA3L11050K258248	Versionname:	3 TOURING 320dA Eff.Dyn.Ed.163PK Aut.
First Registrationdate:	20/10/2014	Fiscalpower:	
Expertise Mileage:	181162	Power Kw:	120
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3824
Maintenance:	BINNEN 2000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	670,00
-------------------	---------------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Acceptable 0,00



Rear window, Scratch(es), E - Replace 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display