



BMW 5: 1EDD603

Vinnnumber:	WBAFW11050DY52198	Versionname:	5 BER 520dA Start/Stop
First Registrationdate:	25/10/2012	Fiscalpower:	163PK aut
Expertise Mileage:	104854	Power Kw:	120
Bodytype:	Berline	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1206
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Total cost ex VAT	2190,60
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete) 372,60



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Bad repair, Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display