



OPEL Zafira: 1EWR389			
Vinnumber:	WOLPE9EN7D2066286	Versionname:	ZAFIRA TOURER Cosmo 165PK Aut.
First Registrationdate:	9/04/2013	Fiscalpower:	
Expertise Mileage:	170394	Power Kw:	121
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3112
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options	
Radio CD	Central consol F
GPS storage	SD Luggage cover
GPS storage	Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm


Assistance equipment	
Total cost ex VAT	1120,23
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Instruction book, Missing, E - Replace	0,00
--	------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Front bumper, Stone chip(s), Acceptable	0,00
---	------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display

Registration Document, Missing, E - Replace	150,00
---	--------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display