



MINI Mini: 1FCE311

Vinnnumber:	WMWSW310X0T233256	Versionname:	MINI Cooper D 112PK DPF
First Registrationdate:	22/05/2013	Fiscalpower:	
Expertise Mileage:	178548	Power Kw:	82
Bodytype:		Body color:	Burgundy
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3820
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/45/17/88 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	208,80
-------------------	--------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Bump(s), PDR - Knock out without painting 63,00



Door F R, Bump(s), PDR - Knock out without painting 82,80

