



IVECO Daily 40C15: 1DCW919			
Vinnnumber:	ZCFC40A5005903553	Versionname:	DAILY PU2C 40C15 146PK
First Registrationdate:	12/04/2012	Fiscalpower:	3500KG
Expertise Mileage:	215533	Power Kw:	107
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options		
Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection			
Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	NOT OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/75/16/107 R Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment	
Total cost ex VAT	540,88
Sill outer L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sidewall RR (LCV), Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Incomplete, E - Replace	84,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	217,56
---	--------



Interior, Dirty, Acceptable	0,00
-----------------------------	------



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Inner door handle F L, Damaged, E - Replace 54,00



Seat cover F R, Damaged, Smart repair 64,32



Floor covering F L, Worn, Acceptable 0,00



Fuel tank stopper, Damaged, Le - Replace and paint 64,00



Dashboard, Hole, Acceptable 0,00

No pictures to display

Mirror side blinker L, Damaged, E - Replace 28,50



Mirror side blinker R, Damaged, E - Replace 28,50



Rear panel, Bump(s), Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Chemical pollution, Acceptable 0,00



Seat cover F L, Worn, Acceptable 0,00

