



OPEL Astra: 1FAY534

Vinnumber:	W0LPD8EW2D8050242	Versionname:	ASTRA BRE ecoFL.Enjoy Active St/St 110PK
First Registrationdate:	13/05/2013	Fiscalpower:	
Expertise Mileage:	111698	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2323
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/93 V Steel			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	0,00
-------------------	------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing L, Unclassped, N - Mount/Dismount	0,00
---	------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Unclassped, Acceptable	0,00
---	------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Front bumper, Difference in color, Acceptable	0,00
---	------



Tailgate, Bump(s), LI - Repair and paint (complete)	0,00
---	------

